

Oil Field Environmental Incident Summary

Incident: 20160523092221 **Date/Time of Notice:** 05/23/2016 09:22

Responsible Party: Enable Midstream Partners

Well Operator:

Well Name: AR-29 Right of Way

Field Name: KILLDEER

Well File #:

Date Incident: 5/22/2016 **Time Incident:** 10:30

Facility ID Number:

County: DUNN

Twp: 148

Rng: 96

Sec: 5

Qtr:

Location Description: LAT: 47.61529 LONG: -102.94122. AR-29 Pipeline Right of Way.

Submitted By: John Launius

Received By:

Contact Person: John Launius
211 North Robinson Avenue
Suite 150
Oklahoma City, OK 73102

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building: 4 Mile

Distance Nearest Water Well: 4 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	2	Gallons		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk. All released material is contained on the Right of Way.

Areal Extent:

The area impacted is approx 10 ft in length by 5 ft in width with a soil impact depth of 4-6 inches.

Potential Environmental Impacts:

Low to no environmental impact. Soil impact by crude oil is minimum. The impacted soil will be excavated and disposal of in an approved landfill. The impacted area will be restored utilizing compatible materials.

Action Taken or Planned:

A small amount of free standing liquid was cleaned up at the receiver using oil absorbent pads. A standard one call notification has been issued. Due to underground utilities in the impacted area no excavation will occur until the one call has been cleared. Excavation & ROW restoration work should begin on 5/24/2016 (estimated time necessary for one call process to be complete). Our environmental response contractor will provide cleanup services as directed. The contaminated soil will be excavated and placed in containers. Further environmental actions include profile and disposal of the recovered material in an approved landfill.

Wastes Disposal Location: Secure Energy Services, Keene, ND

Agencies Involved:**Updates**

Date: 5/23/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 1 barrel of oil impacted soils along a pipeline right-of-way. Further follow-up needed.

Date: 6/8/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

At location 6/8/2016, at 12:21pm. Walked area of release according to the GPS location listed on report. I did not notice an area of concern. I also did not see an area that appeared to have had a recent cleanup. Will talk to contact to get exact area of release. More follow up required.

Date: 6/29/2016 **Status:** Reviewed - Follow-up Required

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Incorrect location of spill. Talked with Clint Fowler 214-923-9357. Correct lat and long is -102.94091 47.615154. Clint offered to take anyone interested to the exact location.

Date: 7/13/2016 **Status:** Inspection

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 9:30 a.m. 70 degrees F, wind 10-15 mph. Pictures taken. Excavation has taken place around receiver area.

Did not notice any disposal barrels or excess soil left on site.

Will check back in the future for vegetative growth.